

# **SERVICE KING #024 WEST FT WORTH**

To schedule repairs please call 1-866-730-5464 2951 W. LOOP 820 SOUTH, FORT WORTH, TX

> 76116 Phone: (817) 302-5250 FAX: (817) 302-5251

### **Preliminary Estimate**

**Customer: Lawrence, Evan** 

Written By: Brandon Arnold

Insured: Lawrence, Evan

Type of Loss:

Lawrence, Evan

Owner:

Point of Impact: 16 Non-Collision

Policy #: Claim #:

Days to Repair: 0

Workfile ID:

Federal ID:

8b3dda00

751781281

**Inspection Location:** 

Date of Loss:

SERVICE KING #024 WEST FT WORTH

2951 W. LOOP 820 SOUTH FORT WORTH, TX 76116

Repair Facility

(817) 302-5250 Business

**Insurance Company:** 

CUSTOMER PAY

11,111

Good

#### **VEHICLE**

1999 CHEV Silverado 1500 LT Extended Cab 143.5" WB 3D P/U 8-5.3L Gasoline SFI black

License:

2GCEC19T7X1214580

Interior Color:

Mileage In:

Vehicle Out:

DDY1457

Exterior Color:

black

Mileage Out:

State:

VIN:

ΤX

Production Date:

3/1999

Condition:

Job #:

**TRANSMISSION** 

Automatic Transmission

Overdrive **POWER** 

**Power Steering Power Brakes** 

**Power Windows** Power Locks **Power Mirrors Heated Mirrors** 

Power Driver Seat Power Passenger Seat

**DECOR** 

**Dual Mirrors** 

**Body Side Moldings** Privacy Glass

Console/Storage Overhead Console

CONVENIENCE

Air Conditioning Intermittent Wipers

Tilt Wheel Cruise Control Rear Defogger Keyless Entry

Alarm

Message Center

**RADIO** 

AM Radio FM Radio Stereo Search/Seek

CD Player Cassette

**SAFETY** 

Drivers Side Air Bag Passenger Air Bag Anti-Lock Brakes (4)

4 Wheel Disc Brakes

**SEATS** 

**Bucket Seats** 

Reclining/Lounge Seats

Leather Seats **Heated Seats** 

**WHEELS** 

Aluminum/Alloy Wheels

**PAINT** 

Clear Coat Paint

**OTHER** Fog Lamps **TRUCK** 

Rear Step Bumper

# **Customer: Lawrence, Evan**

1999 CHEV Silverado 1500 LT Extended Cab 143.5" WB 3D P/U 8-5.3L Gasoline SFI black

Line		Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	#		SUPPLIED PHOTOS MAY NOT INCLUDE ALL RELATED DAMAGES		1			
2	#		HIDDEN DAMAGES MAY BE FOUND DURING DISASSEMBLY		1			
3	#		DAMAGES NOT SHOWN IN PHOTOS COULD INCREASE OVERALL COSTS		1			
4	#							
5	#		COVID19 Safety Measures		1	25.00 X	1.0	
6	FRONT BUMPI	ER						
7		R&I	R&I bumper assy				1.4	
8		R&I	Cap w/o heavy duty black				0.3	
9	GRILLE							
10		R&I	R&I grille assy				Incl.	
11	FRONT LAMPS	3						
12		R&I	RT Headlamp assy				0.4	
13		R&I	LT Headlamp assy				0.4	
14		R&I	RT Park/turn/side				0.3	
15		R&I	LT Park/turn/side				0.3	
16	HOOD							
17	*	Rpr	Hood Chevrolet w/o hvy duty				<u>4.0</u>	3.0
18			Add for Clear Coat					1.2
19	FENDER							
20	*	Rpr	RT Fender Chevrolet				<u>1.5</u>	2.2
21			Overlap Major Adj. Panel					-0.4
22			Add for Clear Coat					0.4
23	*	Rpr	LT Fender Chevrolet				<u>1.5</u>	2.2
24			Overlap Major Adj. Panel					-0.4
25			Add for Clear Coat					0.4
26		R&I	RT Fender liner 2WD				0.4	
27		R&I	LT Fender liner 2WD				0.4	
28	WINDSHIELD							
29		R&I	Windshield GM tinted				2.0	
30	#		Glass Urethane Kit		1	25.00		
31		R&I	RT Reveal molding				Incl.	
32		R&I	LT Reveal molding				Incl.	
33	CAB							
34	*	Rpr	LT Uniside assy			S	<u>1.5</u>	3.0
35			Overlap Major Adj. Panel					-0.4
36			Add for Clear Coat					0.5
37	*	R&I	LT Body side mldg Chevrolet, 3 door black/chrome				0.3	
38		R&I	LT Moveable glass GM tinted				1.5	

# **Customer: Lawrence, Evan**

1999 CHEV Silverado 1500 LT Extended Cab 143.5" WB 3D P/U 8-5.3L Gasoline SFI black

1999 Ci	HEV Silverado 150	0 LI E	ktended Cab 143.5" WB 3D P/U 8-5.3L Gas	oline SFI black				
39	*	Rpr	Roof panel				<u>8.0</u>	3.2
40			Overlap Major Adj. Panel					-0.4
41	*		Add for Clear Coat					0.6
42		R&I	RT Drip w'strip				0.3	
43		R&I	LT Drip w'strip				0.3	
44		R&I	RT Molding roof joint				0.2	
45		R&I	LT Molding roof joint				0.2	
46	FRONT DOOR							
47	*	Rpr	RT Outer panel				<u>1.5</u>	2.4
48			Overlap Major Adj. Panel					-0.4
49	*		Add for Clear Coat					0.4
50	*	Rpr	LT Outer panel				<u>1.5</u>	2.4
51			Overlap Major Adj. Panel					-0.4
52	*		Add for Clear Coat					0.4
53		R&I	RT Belt w'strip				0.3	
54		R&I	LT Belt w'strip				0.3	
55		Repl	RT Decal "CHEVY 1500"	15733703	1	48.07	0.2	
56		Repl	LT Decal "CHEVY 1500"	15733703	1	48.07	0.2	
57	*	R&I	RT Body side mldg Chevrolet black/chrome				0.3	
58	*	R&I	LT Body side mldg Chevrolet black/chrome				<u>0.3</u>	
59		R&I	RT Mirror painted				0.4	
60		R&I	LT Mirror painted				0.4	
61		R&I	RT Door glass GM				0.5	
62		R&I	LT Door glass GM				0.5	
63		R&I	RT Glass w'strip				0.2	
64		R&I	LT Glass w'strip				0.2	
65		R&I	RT Handle, outside w/o luxury pkg				0.4	
66		R&I	LT Handle, outside w/o luxury pkg				0.4	
67		R&I	RT R&I trim panel				0.4	
68		R&I	LT R&I trim panel				0.4	
69	<b>REAR DOOR</b>							
70	*	Rpr	RT Door shell				<u>1.5</u>	2.1
71			Overlap Major Adj. Panel					-0.4
72	*		Add for Clear Coat					0.3
73		R&I	RT Moveable glass GM deep tint				1.5	
74		R&I	RT R&I trim panel				0.4	
75	BACK GLASS							
76		R&I	Back glass tinted non heated				1.5	
77	#		Glass Urethane Kit		1	25.00		
78	PICK UP BOX							
79		R&I	R&I tailgate assy				0.3	
80		R&I	R&I box assy				2.5	

# **Customer: Lawrence, Evan**

1999 CHEV Silverado 1500 LT Extended Cab 143.5" WB 3D P/U 8-5.3L Gasoline SFI black

				SUBTOTALS		346.55	64.1	40.8
110	#		Hazardous Waste Removal		1	10.00 X		
109	#	Subl	Shop Supplies		1	19.95		
108	#	Rpr	Prime, Block, Sand				4.0	
107	#	Refn	Mask jambs - Double Mask					0.3
106	#	Refn	Mask jambs					0.3
105	#	Rpr	Color tint				0.5	
104	#	Rpr	Adhesive Removal				2.0	
103	#		Cover Car		1	8.00 X	0.2	
102	#		Corrosion Protection		1	15.00	0.3	
101	#		Clips, Fasteners, Retainers		1	15.00		
100	#	Rpr	Clean & Retape Emblems/Moldings				2.0	
99		R&I	Lamp lens				0.2	
98		R&I	LT Combo lamp assy 1/2 & 3/4 ton				0.4	
97		R&I	RT Combo lamp assy 1/2 & 3/4 ton				0.4	
96	REAR LAMPS	DOT	DT Caraba James asset 1/2 0 2/4				0.4	
0.0	DEAD   414DC		black/chrome					
95	*	R&I	LT Body side mldg Chevrolet				<u>0.3</u>	
94	*	R&I	RT Body side mldg Chevrolet black/chrome				<u>0.3</u>	
93	*		Add for Clear Coat					0.
92		Refn	Fuel door					0.
91		R&I	Fuel door				0.3	
90	*		Add for Clear Coat					1.
89	*	Rpr	LT Side panel assy				<u>6.0</u>	6.
88	*		Add for Clear Coat					1.
87	*	Rpr	RT Side panel assy	10111000	-	2071.10	<u>2.0</u>	6.
86		Repl	Nameplate "SILVERADO"	15114063	1	107.46	0.2	
85		R&I	Spoiler				0.3	
84		R&I	Handle				0.4	0.
83	*		Add for Clear Coat					0.
82		Rpr	Tail gate Overlap Major Non-Adj. Panel				2.0	2. -0.

# **NOTES**

Estimate Notes: CE: Michael Crimmins

## **Customer: Lawrence, Evan**

1999 CHEV Silverado 1500 LT Extended Cab 143.5" WB 3D P/U 8-5.3L Gasoline SFI black

## **ESTIMATE TOTALS**

Category	Basis		Rate	Cost \$
Parts				303.55
Body Labor	64.1 hrs	@	\$ 56.00 /hr	3,589.60
Paint Labor	40.8 hrs	@	\$ 56.00 /hr	2,284.80
Paint Supplies	40.8 hrs	@	\$ 44.00 /hr	1,795.20
Miscellaneous				43.00
Subtotal				8,016.15
Sales Tax	\$ 2,098.75	@	8.2500 %	173.15
Grand Total				8,189.30

#### MyPriceLink Estimate ID / Quote ID:

860905746131329024 / 91864160

THIS ESTIMATE IS BASED ON A VISIBLE DAMAGE INSPECTION ONLY. UPON STARTING REPAIRS, THE POSSIBILITY OF HIDDEN DAMAGE MAY REQUIRE ADDITIONAL PARTS AND/OR LABOR NECESSARY TO COMPLETE THE REPAIRS.

#### **Customer: Lawrence, Evan**

1999 CHEV Silverado 1500 LT Extended Cab 143.5" WB 3D P/U 8-5.3L Gasoline SFI black

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DE1GH99, CCC Data Date 08/17/2021, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (\*) or Double Asterisk (\*\*) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2022 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

#### SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

### SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

### OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

# **Customer: Lawrence, Evan**

1999 CHEV Silverado 1500 LT Extended Cab 143.5" WB 3D P/U 8-5.3L Gasoline SFI black

## **PARTS SUPPLIER LIST**

Line	Supplier	Description	Price
56	AutoNation Chevrolet North Richland Hills	#15733703	\$ 48.07
	7769 Boulevard 26	LT Decal "CHEVY 1500"	
	North Richland Hills TX 76180	Quote: 995187034	
		Expires: 09/27/21	
86	AutoNation Chevrolet North Richland Hills	#15114063	\$ 107.46
	7769 Boulevard 26	Nameplate "SILVERADO"	
	North Richland Hills TX 76180	Quote: 995187842	
		Expires: 09/27/21	